

Operations Report

Hickory Log Creek Board of Managers Meeting
February 19, 2025

Reservoir Update

- Since November 20, 2024
 - Pumpage to the reservoir: 0.00 MG
 - Releases from the reservoir: 00.00 MG
- Current elevation: 1060.0 MSL
 - Full pool is 1060.0 MSL

HLC Asset Renewal and Replacement (AR&R) Planning

- SCADA server and software upgrade:
 - This project has been delayed and will continue through 2025.
- Intake vault improvement:
 - The mandatory Pre-Bid meeting occurred 2/4/25. The bid opening is scheduled for 2/21/25.
- Instrumentation replacement:
 - Schnabel is preparing the contract for approval.

Other Information

- Joe Powell Services performed quarterly HVAC PMs at the pump station. The service contract was also renewed for 2025.
- CCMWA Instrumentation and Controls removed the downstream Sonde for repairs. The Sonde will be reinstalled upon completion of these repairs.
- During the February 12th rainstorms, the Etowah River flooded over the intake vault, leaving it covered by sand and sedimentation. HLC staff will work with CCMWA Maintenance to schedule staff to bring equipment to clean the area.
- HLC staff is scheduled to collect reservoir Sonde profile samples in March.
- HLC staff has completed all lubrication PMs on all ring jet and sluice gate valves.