


## Canton Water Reclamation Facility Improvements Project Construction Progress Photos



View of Filter Cell #8 being cleaned.  
January 15, 2015



View of 36" RCP Storm Pipe on soccer field  
January 29, 2015



View of form installation at SBR #4  
February 5, 2015



View of reinforcing steel being installed in slab  
February 9, 2015



## Canton Water Reclamation Facility Improvements Project Construction Progress Photos



Concrete Placement for slab pour in SBR #4  
February 10, 2015



Concrete Placement for Slab Pour A in SBR #4  
February 10, 2015



View of 36" RCP storm drain installation near MH A-1  
February 18, 2015



View of sand removal from filter #7  
February 17, 2015